

Spool bar 1 per spool



Spool pin 2 per spool



5" position shown  
6" position not being used



Picture rotated 90 degrees



## Complete assembled unit with two spools

### Assembly directions

- (1) Bolt left side frame to cross support bars as illustrated using 2-3/8-16 bolts with flat and lock washer
- (2) bolt right support frame same as step 1
- (3) Assemble spools, slide spool bar thru spool halves large ring to outside install spool pin in 5" position or 6" position as needed.
- (4) Load spool onto upright 2 places.